

Panama Maritime Authority
General Directorate of Merchant Marine
Control and Compliance Department

MERCHANT MARINE CIRCULAR MMC-142

To: Ship-owner/Operators, Company Security Officers, Legal

Representatives of Panamanian Flagged Vessels, Panamanian Merchant Marine Consulates and Recognized Organization (RO´s).

Subject: Emergency Escape Breathing Devices (EEBD).

Reference: Law No. 7 of October 27, 1977 – SOLAS.

MSC.1/Circ.1432. May 31, 2012 MSC/Circ.1081. June 13, 2003 MSC.1/Circ.849. May 1998

1. Purpose.

1.1. This Merchant Marine Circular replaces **MMC-119**.

2. Scope.

- 2.1. The 2000 amendments to SOLAS 74, Chapter II-2, Reg. 13 require Emergency Escape Breathing Devices (EEBD) which will be used for escape from a compartment that has a hazardous atmosphere. The EEBD have become mandatory under the new amendments for all ships to which the safety equipment certificate is required.
- **2.2.** Applies to all Panamanian ships and offshore units to which the International Convention for the Safety of Life at Sea, 1974, as amended (SOLAS) applies.
- **2.3.** Offshore units certified under the 1979, 1989 or 2009 Code for the Construction and Equipment of Mobile Offshore Drilling Units (MODU Code) shall be provided with EEBDs as if they were SOLAS certified.

3. Requirements:

3.1. Number of EEBDs.

PanCanal Building Albrook, Panama City Republic of Panama Panama Ship Registry

© ShipPanama



The application of EEBDs provisions onboard Panama flag ships shall be as follows:

- **3.1.1** At least two (2) EEBDs in accommodation spaces of cargo ships and one (1) spare EEBD. Applicable to new and existing ships.
- **3.1.2.** At least two (2) EEBDs per main vertical zone, and a total of two (2) spare EEBDs. Applicable to new and existing passenger ships carrying not more than 36 passengers.
- **3.1.3.** At least four (4) EEBDs per main vertical zone, and a total of two (2) spare EEBDs. Applicable to new and existing passenger ships carrying more than 36 passengers.
- **3.2.** For the purpose of this requirement (based on UI MSC/Circ.1081), the minimum number of EEBDs required on machinery spaces shall be as follows:
 - **3.2.1.** One (1) EEBD at the engine control room if located inside the machinery space;
 - **3.2.2.** One (1) EEBD at the machine shop or work shop area. If there is, however, a direct access to an escape way from the workshop, an EEBD is not required; and
 - **3.2.3.** One (1) EEBD located near the escape ladder used a second means of escape from the machinery space.

If the ship has a machinery space with more than one deck, then one (1) EEBD for each deck shall be placed at the same area as in point (3.4.3).

4. Additional Spares.

- **4.1.** Additional spares are applicable to new and existing ships:
 - **4.1.1.** Ships with 10 or less EEBDs (1) on board shall carry at least one (1) spare device as it is indicated in point 3 (except for passenger ships).
 - **4.1.2.** Ships with 11 to 20 EEBDs (1) on board shall carry at least two (2) spare devices.
 - **4.1.3.** Ships with more than 20 EEBDs(*) on board shall carry spares equal to at least 10% of the total applicable EEBDs (excluding spares indicated in point 3) but no more than 4 spares will be required.
- **4.2.** Additional to the above requirements, the EEBD shall have service duration of at least 10 minutes. Also, the number and location of EEBDs and spares shall be indicated in the fire control plan.
- **4.3.** For existing ships, the requirement is to be complied with by the first survey after 1 July 2002. For more reference, the 2000 amendments to SOLAS 74, Chapter II-2, Reg. 1.2.2 clarify the applicable requirements to existing ships.





- **4.4.** The detailed technical standards for the EEBD are separately provided in a mandatory code called "The International Code for the Fire Safety System (FSS Code)" adopted simultaneously.
- **4.5.** Note: "New ships" cited above means ships constructed on or after 1 July 2002 and "Existing ships" means ships constructed prior to that date.
- **4.6.** Authorized Organizations are instructed to follow the above mentioned guidelines, before issuing the appropriate certificate.
- 5. Training (as per the IMO MSC.1/Circ.849 May 1998) SOLAS Amendment 2012 II-2/15.2.2.2.
 - **5.1.** Training in the use of the EEBD should be considered as a part of basic safety training. At least one (1) EEBD training device shall be used for training purpose at first Safety Equipment survey on or after 1st May 2018.
 - **5.2.** This unit device will be in addition to EEBDs required for the machinery and accommodation spaces unless onboard means of recharging EEBD is provided. If the rechargeable means is provided on board in alignment with the manufacturer's instructions, then no additional EEBD cylinder for training will be necessary, considering that there are several types of them (Additional mask and associated devices.
- *Spare EEBDs mentioned in section 3 are not to be included in total number for training is still required, although rechargeable means is provided). One (1) of EEBD must be marked for training.
 - **5.3.** Personnel should be trained to immediately don an EEBD prior to exiting a space when the atmosphere becomes life threatening. This is necessary due to the possibility of encountering smoke during escape. Such training should be accomplished by scheduling routine escape drills for crew members working in the engineering or machinery spaces.
 - **5.4.** An EEBD may also be used to escape from a machinery space due to an accidental release of a fixed CO2 system and can be carried by firefighters for the sole purpose of providing the device to personnel in need of emergency assistance.

6. Survey:

- **6.1.** During Safety Equipment surveys the Recognized Organization shall verify that:
- **6.1.1**. the manufacturer's instructions for the EEBDs are provided and are readily available on board;

PanCanal Building Albrook, Panama City Republic of Panama Panama Ship Registry

@ShipPanama



- **6.1.2.** the EEBDs have been inspected and maintained in accordance with the manufacturer's instructions and this Bulletin;
- **6.1.3.** the records of inspection, maintenance and testing are available and up to date; iv. spare EEBDs are provided in accordance with paragraph
- **6.2.** Recognized Organizations shall notify the Panama Administration, with relevant recommendations, when a Panamanian ship does not satisfy the requirements for periodical inspections and testing or carriage of spares, prior to the issue or endorsement of a Cargo Ship Safety Equipment Certificate, Passenger Ship Safety Certificate or any other statutory certificate that relates to safety equipment (e.g. MODU/MOU Safety certificates).

7. Inspection and Testing:

- **7.1.** All EEBDs shall be inspected by a competent person at least annually.
- **7.2.** Maintenance and servicing of EEBDs shall be carried out in accordance with the manufacturer's instructions.
- **7.3.** Hydrostatic pressure testing of EEBD cylinders shall be undertaken at least once every five years, or in accordance with the manufacturer's instructions if such testing is required on a more frequent basis. The test pressure and test date shall be clearly and permanently marked on the cylinder.
- **7.4.** Where EEBDs are fitted with a small capacity oxygen cartridge and manufacturers specify a fixed service life without scheduled hydrostatic pressure testing (e.g. "Ocenco" M-20.2), hydrostatic testing is not required.

November, 2023 – Revised text and reference.

January, 2019 – paragraphs of point 4 renumbered, omission of previous text in 1st paragraph of section 4 revised and number assigned to sub-paragraphs in point 4.

January, 2019 - Point 5

June, 2018 - Point 4, Point 5

March, 2018 - Point 4, Point 5.

January, 2018 – Point 3 a), b) and c) amended as well as 3 d) ii); subtitle 4 amended, and point 5 "Training added" as per IMO MSC.1/Circ.849 – may, 1998.

June, 2013.

November, 2005 - (revised)

April, 2002.





Inquiries concerning the subject of this Merchant Marine Circular or any other request should be forward to:

> **SEGUMAR PANAMA** Directorate General of Merchant Marine Panama Maritime Authority

Phone: (507) 501-5348 / 50 / 61 / 62

E-mail: rberrocal@segumar.com / deputychief@segumar.com / Website: https://panamashipregistry.com/circulars/





