

Subject :

LIST OF CURRENT NK
TECHNICAL INFORMATION

NK TECHNICAL INFORMATION

No. : 1 6 6

Date : 25 August 1995

To Shipowners and Shipbuilders concerned

The total number of NK TECHNICAL INFORMATION issued by NK has reached to more than 160. Meanwhile, some of these issues are no longer current and to be disregarded.

Consequently, an updated list of prevailing back numbers has been prepared and enclosed herewith for your reference.

We hope this list be helpful to you, but should you have any questions or need further information, please feel free to contact this NK Head Office or any branch office at your area.

encl.

ClassNK

NIPPON KAIJI KYOKAI
4-7, KIOI-CHO, CHIYODA-KU,
TOKYO 102, JAPAN.

TEL : 03-3230-1201
FAX : 03-3230-3524
TELEX : 22975 CLASSNKJ
2324280 CLASNKJ
CABLE : CLASSNK TOKYO

List of NK Technical Information

No.	Subject	Date
52	Fiberglass (GRP) Hatch Cover	28 Aug. 1986
53	Annual Inspections of Crew Lifts fitted on board Greek Flag Ships	5 Nov. 1986
59	Fire Extinguishers and Spare Fire Extinguishers/Spare Charges for Liberian/Panamanian Flag Ships	15 Jun. 1987
90	Care and Survey of Hatch Covers of Dry Cargo Ships- Guidance to Owners	27 Dec. 1990
91	Requirements of 1983 Amendments to SOLAS 74 for existing ships	15 Feb. 1991
98	Amendments to the SOLAS 1974, as amended	14 Nov. 1991
101	U.S. Regulations on Vapor Emission Control System and Certificate of Compliance	29 Oct. 1991
102	Application of Chapters III and IV of 1988 Amendments to the SOLAS 1974 concerning Radio communications for GMDSS, for ships flying flags of other than Japanese	27 Jan. 1992
104	Amendments to Chapter II-2/Regulations 18.7 of SOLAS 1974	31 Jan. 1992
105	Amendments to Annex I of MARPOL 1973/78 as amended (Double Hull Tankers etc.)	30 Apr. 1992
106	IMO Resolution regarding the Use of CFCs and Halons on board Ships	18 Jun. 1992
107	Regulation 18.7 of Chapter II-2 of SOLAS 1974 as amended	16 Jun. 1992
108	Regulation 18.7 of Chapter II-2 of SOLAS 1974 as amended	28 Oct. 1992
109	NK Emergency Technical Assistance Service (ETAS)	10 Dec. 1992
111	Survey Request from the Port State under Port State Control	4 Feb. 1993
112	Regulation 18.7 of Chapter II-2 of SOLAS 1974 as amended	5 Feb. 1993
115	Fire Extinguishing Arrangements of Paint Lockers and Flammable Liquid Stores for Hong Kong Flag Ships (Reg.18.7 of Chap.II-2,SOLAS)	28 Apr. 1993
118	Required qualification and numbers of Radio personnel on board the GMDSS ship	23 Jun. 1993
122	Installation of a satellite EPIRB, model KANNAD 406 FH, manufactured by SERPE-IESM Ltd., France	1 Nov. 1993
126	Confirmation of Calibration Records of Pressure Gauges on Board Ships	25 Jan. 1994
127	Lifeboats Maximum Lowering Speed for New Panamanian flag Ships (as regard to 74 SOLAS 83 Amendments III/48.2.7)	14 Jan. 1994
128	1991 Amendments to the SOLAS 1974 concerning Pilot Ladders and Mechanical Pilot Hoists (Reg.V/17)	14 Jan. 1994

No.	Subject	Date
131	IMO Guidelines and Specifications for Pollution Prevention Equipment for Machinery Space Bilges of Ships	25 Feb. 1994
133	(available only in Japanese)	
134	The requirements of Reg.III/6.2 of 88 Amendments to 74 SOLAS for existing ships flying other flags than Japanese flag	10 Apr. 1994
135	Revised ID assigning method for satellite EPIRBs on ships flying Panamanian flag	9 May 1994
136	Additional Requirements of GMDSS for Greek flag ships	10 May 1994
137	1991 Amendments to the 1974 SOLAS concerning Pilot Ladders and Mechanical Pilot Hoists (Reg.V/17)	11 May 1994
139	1992 Amendments to the International Convention for the Safety of Life at Sea, 1974	20 Jun. 1994
140	Continuous Hull Survey System for Oil Tankers, Bulk Carriers and Ore Carriers	14 Jun. 1994
141	CO ₂ Release Mechanism:-1992 Amendments to 74 SOLAS	30 Jun. 1994
144	Arrangements for Supplying Heading Information to Emergency Steering Positions for Non-Japanese Ships	15 Aug. 1994
145	Surveys of Oil Tankers, Bulk Carriers and Ore Carrier	15 Aug. 1994
146	Revisions of the Performance Standards for Two-way VHF Radiotelephone Apparatus and 406MHz Satellite EPIRBs	29 Aug. 1994
147	General Emergency Alarm Systems for Ships Flying Other Flags than Japanese Flag	14 Sep. 1994
149	Two-way VHF Radiotelephone Apparatus installed on board in accordance with Requirements of 1988 Amendments to 1974 SOLAS	24 Oct. 1994
150	Indication of the identity code on 406MHz Satellite EPIRB	26 Oct. 1994
152	Measures for Providing Heading Information at Emergency Steering Positions	31 Oct. 1994
153	Installation of Radar capable of operating in 9GHz frequency band for ships flying other flags than Japanese flag	14 Nov. 1994
155	Shipboard Oil Pollution Emergency Plan	14 Dec. 1994
156	Measures for Providing Heading Information at Emergency Steering Positions	10 Jan. 1995
157	Requirements of Hong Kong Government for Immersion Suits and Thermal Protective Aids	30 Jan. 1995
159	Special Requirements of the Panamanian Government for the Two-way Radiotelephone Apparatus for Acceptance till 1 February 1999	20 Apr. 1995
160	Requirements of Maltese Government for Immersion Suits and Thermal Protective Aids	28 Apr. 1995

No.	Subject	Date
161	Condition Survey for Bulk Carriers over 18 years old of ages entering into Brazilian Ports	10 May 1995
162	Revised requirements for Radio personnel required on board Panamanian ships which fully apply GMDSS	1 June 1995
163	Exemption from installation of a Radio Direction Finder on Panamanian Ships	10 July 1995
164	Required Qualifications and Numbers of Radio Personnel on board GMDSS Ships	3 Aug. 1995
165	Condition Survey for Bulk Carriers over 18 years old of ages entering into Brazilian Ports (No.2)	27 July 1995

VOID