

Subject :

LIST OF CURRENT NK
TECHNICAL INFORMATION

NKTECHNICAL INFORMATION

No. : 1 8 4

Date : 20 May 1996

To Shipowners and Shipbuilders concerned

Enclosed is an updated list of prevailing back numbers of NK TECHNICAL INFORMATION issued by NK as of 15 May 1996.

We hope this list be helpful to you, but should you have any questions or need further information, please feel free to contact this NK Head Office or any branch office at your area.

encl.

VOID

ClassNK

NIPPON KAIJI KYOKAI
4-7, KIOI-CHO, CHIYODA-KU,
TOKYO 102, JAPAN.

TEL: 03-3230-1201
FAX: 03-3230-3524
TELEX: J22975 CLASSNK
2324280 CLASNKJ
CABLE: CLASSNK TOKYO

List of NK Technical Information

No.	Subject	Date
5 2	Fiberglass (GRP) Hatch Cover	28 Aug. 1986
5 3	Annual Inspections of Crew Lifts fitted on board Greek Flag Ships	5 Nov. 1986
5 9	Fire Extinguishers and Spare Fire Extinguishers/Spare Charges for Liberian/Panamanian Flag Ships	15 Jun. 1987
9 0	Care and Survey of Hatch Covers of Dry Cargo Ships - Guidance to Owners	27 Dec. 1990
9 1	Requirements of 1983 Amendments to SOLAS 74 for existing ships	15 Feb. 1991
9 8	Amendments to the SOLAS 1974, as amended	14 Nov. 1991
1 0 2	Application of Chapters III and IV of 1988 Amendments to the SOLAS 1974 concerning Radio communications for GMDSS, for ships flying flags of other than Japanese	27 Jan. 1992
1 0 4	Amendments to Chapter II-2/Regulations 18.7 of SOLAS 1974	31 Jan. 1992
1 0 5	Amendments to Annex I of MARPOL 1973/78 as amended (Double Hull Tankers etc.)	30 Apr. 1992
1 0 6	IMO Resolution regarding the Use of GFCs and Halons on board Ships	18 Jun. 1992
1 0 8	Regulation 18.7 of Chapter II-2 of SOLAS 1974 as amended	28 Oct. 1992
1 0 9	NK Emergency Technical Assistance Service (ETAS)	10 Dec. 1992
1 1 1	Survey Request from the Port State under Port State Control	4 Feb. 1993
1 1 2	Regulation 18.7 of Chapter II-2 of SOLAS 1974 as amended	5 Feb. 1993
1 1 5	Fire Extinguishing Arrangements of Paint Lockers and Flammable Liquid Stores for Hong Kong Flag Ships (Reg.18.7 of Chap.II-2, SOLAS)	28 Apr. 1993
1 2 2	Installation of a satellite EPIRB, model KANNAD 406 FH, manufactured by SERPE-IESM Ltd., France	1 Nov. 1993
1 2 6	Confirmation of Calibration Records of Pressure Gauges on Board Ships	25 Jan. 1994
1 2 7	Lifeboats Maximum Lowering Speed for New Panamanian flag Ships (as regard to 74 SOLAS 83 Amendments III/48.2.7)	14 Jan. 1994
1 3 1	IMO Guidelines and Specifications for Pollution Prevention Equipment for Machinery Space Bilges of Ships	25 Feb. 1994

No.	Subject	Date
1 3 3	(available only in Japanese)	1 Mar. 1994
1 3 4	The requirements of Reg.III/6.2 of 88 Amendments to 74 SOLAS for existing ships flying other flags than Japanese flag	10 Apr. 1994
1 3 5	Revised ID assigning method for satellite EPIRBs on ships flying Panamanian flag	9 May 1994
1 3 6	Additional Requirements of GMDSS for Greek flag ships	10 May 1994
1 3 9	1992 Amendments to the International Convention for the Safety of Life at Sea, 1974	20 Jun. 1994
1 4 1	CO ₂ Release Mechanism:-1992 Amendments to 74 SOLAS	30 Jun.1994
1 4 4	Arrangements for Supplying Heading Information to Emergency Steering Positions for Non-Japanese Ships	15 Aug. 1994
1 4 5	Surveys of Oil Tankers, Bulk Carriers and Ore Carriers	15 Aug. 1994
1 4 6	Revisions of the Performance Standards for Two-way VHF Radiotelephone Apparatus and 406MHz Satellite EPIRBs	29 Aug. 1994
1 4 9	Two-way VHF Radiotelephone Apparatus installed on board in accordance with Requirements of 1988 Amendments to 1974 SOLAS	24 Oct. 1994
1 5 0	Indication of the identity code on 406MHz Satellite EPIRB	26 Oct. 1994
1 5 2	Measures for Providing Heading Information at Emergency Steering Positions	31 Oct. 1994
1 5 3	Installation of Radar capable of operating in 9GHz frequency band for ships flying other flags than Japanese flag	14 Nov. 1994
1 5 5	Shipboard Oil Pollution Emergency Plan	14 Dec. 1994
1 5 6	Measures for Providing Heading Information at Emergency Steering Positions	10 Jan. 1995
1 5 7	Requirements of Hong Kong Government for Immersion Suits and Thermal Protective Aids	30 Jan. 1995
1 5 9	Special Requirements of the Panamanian Government for the Two-way Radiotelephone Apparatus for Acceptance till 1 February 1999	20 Apr. 1995
1 6 0	Requirements of Maltese Government for Immersion Suits and Thermal Protective Aids	28 Apr. 1995
1 6 1	Condition Survey for Bulk Carriers over 18 years old of ages entering into Brazilian Ports	10 May 1995

No.	Subject	Date
1 6 3	Exemption from installation of a Radio Direction Finder on Panamanian Ships	10 Jul. 1995
1 6 5	Condition Survey for Bulk Carriers over 18 years old of ages entering into Brazilian Ports (No.2)	27 Jul. 1995
1 6 7	Spare charges for Portable Fire Extinguishers for Maltese Flag Ships	1 Sep. 1995
1 6 8	Good Preparation For Surveys & Enhanced Maintenance On Board Ships	8 Sep. 1995
1 6 9	Required Qualifications and Numbers of Radio Personnel on board GMDSS Ships	20 Oct. 1995
1 7 0	General Emergency Alarm Systems for Ships Flying Other Flags than Japanese Flag	22 Nov. 1995
1 7 1	Exemption from Installation of Radio Direction Finder and Radio equipment for homing on Bahamas Flag Ships	28 Dec. 1995
1 7 2	A pump used both for an oily water separator and sludge transfer	21 Dec. 1995
1 7 3	SOLAS 1994 Amendment: Emergency Towing Arrangements on Tankers	25 Dec. 1995
1 7 4	Enactment of the Rules for High Speed Craft (for craft flying non-Japanese flag)	21 Dec. 1995
1 7 6	Testing and Survey of CO ₂ and Halon Containers for the Cypriot Flag ships	25 Jan. 1996
1 7 7	Assessment for Safety Management System according to the ISM Code (Revised)	1 Feb. 1996
1 7 8	Cargo Securing Manuals	29 Feb. 1996
1 7 9	Amendment of Rules for the Survey and Construction of Steel Ships and Other Rules	1 Apr. 1996
1 8 0	Cargo Securing Manuals	22 Apr. 1996
1 8 1	Marine Safety Initiatives Implemented by All IACS Member Societies	15 May 1996
1 8 2	Spare Cylinders of Self-contained Breathing Apparatus for Malaysian Flag Ships	8 Apr. 1996
1 8 3	Exemption from Installation of a Radio Direction Finder & Radio Equipment for Homing on Barbados Flag	8 May 1996