

Subject :

LIST OF CURRENT NK  
TECHNICAL INFORMATION

# NKTECHNICAL INFORMATION

No. : No. 236

Date : 15 November 1997

To Shipowners and Shipbuilders concerned

Enclosed is an updated list of prevailing back numbers of NK TECHNICAL INFORMATION issued by NK as of 30 October 1997.

We hope this list be helpful to you, but NK Technical Information does not always cover the detailed requirements from each flag states. Therefore, where you refer to such information, or should you have any other questions and need further information, please feel free to contact NK Head Office as below or any branch office at your area.

| <u>Name of Dept.</u>              | <u>Abb.</u> | <u>TEL No.</u>     | <u>FAX No.</u>  |
|-----------------------------------|-------------|--------------------|-----------------|
| Hull Dept.                        | HLD         | +81-3-5226-2017/18 | +81-3-5226-2019 |
| Material and Equipment Dept.      | EQD         | +81-3-5226-2020    | +81-3-5226-2019 |
| Development Dept.                 | DVD         | +81-3-5226-2025    | +81-3-5226-2024 |
| Survey Dept.                      | SVD         | +81-3-5226-2027/28 | +81-3-5226-2029 |
| Classification Dept.              | CLD         | +81-3-5226-2032/33 | +81-3-5226-2030 |
| Ship Management Assessing Div.    | SMD         | +81-3-5226-2034    | +81-3-5226-2030 |
| Business Coordination Dept.       | BCD         | +81-3-5226-2038    | +81-3-5226-2039 |
| Marine & Industrial Service Dept. | MISD        | +81-3-5226-2041    | +81-3-5226-2039 |

When you need a copy of back numbers, please contact Business Coordination Department.

encl.

**ClassNK** NIPPON KAIJI KYOKAI  
4-7, KIOI-CHO, CHIYODA-KU,  
TOKYO102, JAPAN.

TELEX : 22975 CLASSNKJ  
2324280 CLASNKJ  
CABLE : CLASSNK TOKYO

# LIST OF CURRENT NK TECHNICAL INFORMATION

| N o . | Subject                                                                                                                                                                | Date/<br>Contact    |
|-------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|
| 5 3   | Annual Inspections of Crew Lifts fitted on board Greek Flag Ships                                                                                                      | 5 Nov. 1986<br>EQD  |
| 5 9   | Fire Extinguishers and Spare Fire Extinguishers/Spare Charges for Liberian/<br>Panamanian Flag Ships                                                                   | 15 Jun. 1987<br>EQD |
| 1 0 2 | Application of Chapters III and IV of 1988 Amendments to the SOLAS 1974<br>concerning Radio communications for GMDSS, for ships flying flags of other<br>than Japanese | 27 Jan. 1992<br>EQD |
| 1 0 9 | NK Emergency Technical Assistance Service (ETAS)                                                                                                                       | 10 Dec. 1992<br>SVD |
| 1 1 1 | Survey Request from the Port State under Port State Control                                                                                                            | 4 Feb. 1993<br>SVD  |
| 1 2 7 | Lifeboats Maximum Lowering Speed for New Panamanian flag Ships (as regard<br>to 74 SOLAS 83 Amendments III/48.2.7)                                                     | 14 Jan. 1994<br>EQD |
| 1 3 5 | Revised ID assigning method for satellite EPIRBs on ships flying Panamanian<br>flag                                                                                    | 9 May 1994<br>EQD   |
| 1 3 6 | Additional Requirements of GMDSS for Greek flag ships                                                                                                                  | 10 May 1994<br>EQD  |
| 1 4 4 | Arrangements for Supplying Heading Information to Emergency Steering<br>Positions for Non-Japanese Ships                                                               | 15 Aug. 1994<br>EQD |
| 1 4 8 | Application to Amendment of Panama Canal Tonnage Rule                                                                                                                  | 1 Sep. 1996<br>HLD  |
| 1 4 9 | Two-way VHF Radiotelephone Apparatus installed on board in accordance with<br>Requirements of 1988 Amendments to 1974 SOLAS                                            | 24 Oct. 1994<br>EQD |
| 1 5 2 | Measures for Providing Heading Information at Emergency Steering Positions                                                                                             | 31 Oct. 1994<br>EQD |
| 1 5 5 | Shipboard Oil Pollution Emergency Plan                                                                                                                                 | 14 Dec. 1994<br>SVD |
| 1 5 6 | Measures for Providing Heading Information at Emergency Steering Positions                                                                                             | 10 Jan. 1995<br>EQD |
| 1 5 7 | Requirements of Hong Kong Government for Immersion Suits and Thermal<br>Protective Aids                                                                                | 30 Jan. 1995<br>EQD |
| 1 5 9 | Special Requirements of the Panamanian Government for the Two-way<br>Radiotelephone Apparatus for Acceptance till 1 February 1999                                      | 20 Apr. 1995<br>EQD |

| N o . | Subject                                                                                                    | Date/<br>Contact     |
|-------|------------------------------------------------------------------------------------------------------------|----------------------|
| 1 6 0 | Requirements of Maltese Government for Immersion Suits and Thermal Protective Aids                         | 28 Apr. 1995<br>EQD  |
| 1 6 5 | Condition Survey for Bulk Carriers over 18 years old of ages entering into Brazilian Ports (No.2)          | 27 Jul. 1995<br>MISD |
| 1 6 7 | Spare charges for Portable Fire Extinguishers for Maltese Flag Ships                                       | 1 Sep. 1995<br>EQD   |
| 1 6 8 | Good Preparation For Surveys & Enhanced Maintenance On Board Ships                                         | 8 Sep. 1995<br>SVD   |
| 1 6 9 | Required Qualifications and Numbers of Radio Personnel on board GMDSS Ships                                | 20 Oct. 1995<br>EQD  |
| 1 7 0 | General Emergency Alarm Systems for Ships Flying Other Flags than Japanese Flag                            | 22 Nov. 1995<br>EQD  |
| 1 7 1 | Exemption from Installation of Radio Direction Finder and Radio equipment for homing on Bahamas Flag Ships | 28 Dec. 1995<br>EQD  |
| 1 7 2 | A pump used both for an oily water separator and sludge transfer                                           | 21 Dec. 1995<br>SVD  |
| 1 7 3 | SOLAS 1994 Amendment. Emergency Towing Arrangements on Tankers                                             | 25 Dec. 1995<br>EQD  |
| 1 7 6 | Testing and Survey of CO <sub>2</sub> and Halon Containers for the Cypriot Flag ships                      | 25 Jan. 1996<br>EQD  |
| 1 8 0 | Cargo Securing Manuals                                                                                     | 8 Apr. 1996<br>DVD   |
| 1 8 1 | Marine Safety Initiatives Implemented by All IACS Member Societies                                         | 15 Apr. 1996<br>BCD  |
| 1 8 2 | Spare Cylinders of Self-contained Breathing Apparatus for Malaysian Flag Ships                             | 8 Apr. 1996<br>EQD   |
| 1 8 3 | Exemption from Installation of a Radio Direction Finder & Radio Equipment for Homing on Barbados Flag      | 8 May 1996<br>EQD    |
| 1 8 5 | Suspension of Class                                                                                        | 1 Jun. 1996<br>CLD   |
| 1 8 6 | Revised Qualifications and Number of Radio Personnel Required on Board Vanuatu GMDSS Ships                 | 25 Jun. 1996<br>EQD  |

| N o . | Subject                                                                                                                                                                     | Date/<br>Contact     |
|-------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|
| 1 8 7 | Lifejackets for Hong Kong Registered Ships Fitted with Free-fall Lifeboats                                                                                                  | 1 Jul. 1996<br>EQD   |
| 1 8 9 | Discussions in IMO and IACS on Bulk Carrier Safety                                                                                                                          | 10 Jul. 1996<br>BCD  |
| 1 9 0 | Positioning of Sidelights on Hong Kong Flag Container Ships                                                                                                                 | 25 Jul. 1996<br>EQD  |
| 1 9 1 | REQUIREMENTS OF GMDSS FOR HONG KONG REGISTERED SHIPS                                                                                                                        | 30 Jul. 1996<br>EQD  |
| 1 9 2 | Cargo Securing Manual                                                                                                                                                       | 17 Jul. 1996<br>DVD  |
| 1 9 3 | Qualifications and Numbers of Radio Personnel Required on board Malaysian Flag and Myanmar Flag GMDSS Ships                                                                 | 5 Aug. 1996<br>EQD   |
| 1 9 4 | Enhanced Survey Programme for Bulk Carriers                                                                                                                                 | 26 Aug. 1996<br>SVD  |
| 1 9 5 | Exemption from the requirements of Radio Direction-finding Apparatus, Automatic Radar Plotting Aid, Radar, etc. of the Liberian and Marshall Islands Flag Ships             | 21 Aug. 1996<br>SVD  |
| 1 9 7 | Requirement for Anchor Lights and Not Under Command Lights on Panamanian Flag Ships                                                                                         | 28 Jun. 1996<br>EQD  |
| 1 9 8 | IMPLEMENTATION OF MANEUVERING PERFORMANCE CAPABILITY TESTS FOR TANK VESSELS WITHOUT DOUBLE HULLS CARRYING OILS OF 5,000 GROSS TONNAGE AND MORE WHICH ENTER INTO U.S. WATERS | 17 Oct. 1996<br>MISD |
| 1 9 9 | Maintenance for electro-hydraulic cranes                                                                                                                                    | 11 Nov. 1996<br>EQD  |
| 2 0 0 | Approval of Drawings/Documents Related to GMDSS Radio Equipment to be Installed on Board Non-Japanese GMDSS Ships                                                           | 20 Nov. 1996<br>EQD  |
| 2 0 3 | New requirements for bulk carrier                                                                                                                                           | 25 Dec. 1996<br>SVD  |
| 2 0 5 | Qualifications and Number of Radio Personnel Required on board Libyan Flag GMDSS Ships                                                                                      | 6 Feb. 1997<br>EQD   |
| 2 0 6 | Statutory Surveys on Ships Changing to Singapore registry                                                                                                                   | 3 Feb. 1997<br>BCD   |
| 2 0 7 | Means for Rapid and Safe Recovery of Rescue Boats of Hong Kong Registered Ships                                                                                             | 21 Feb. 1997<br>EQD  |

| No.   | Subject                                                                                                                           | Date/<br>Contact    |
|-------|-----------------------------------------------------------------------------------------------------------------------------------|---------------------|
| 2 0 8 | Reserve Sources of Energy for GMDSS Radio Equipment on board Greek Flag Ships                                                     | 25 Feb. 1997<br>EQD |
| 2 0 9 | Exemption from installation of a Radio Direction Finder on Singapore Flag Ships                                                   | 28 Feb. 1997<br>EQD |
| 2 1 0 | Installation of the Loading Instruments Onboard Existing Bulk Carrier                                                             | 14 Mar. 1997<br>SVD |
| 2 1 1 | Amendments to SOLAS Convention issued in 1997                                                                                     | 10 Apr. 1997<br>BCD |
| 2 1 2 | Languages to be used on Safety Plans on board Malaysian flag vessels                                                              | 10 Apr. 1997<br>BCD |
| 2 1 3 | Postponement of Emergency Towing Arrangements (ETA) for Tankers                                                                   | 1 May 1997<br>SVD   |
| 2 1 4 | Amendment of Guidance for the Approved and Type Approval of Materials and Marine Use and Enacted to Guidance for Survey Equipment | 23 May 1997<br>EQD  |
| 2 1 6 | Exemption from Requirements of Chapter IV and V of SOLAS Convention for Panamanian Flag Ships                                     | 30 June 1997<br>EQD |
| 2 1 7 | Acceptance of applications for Shipboard Audits based on the ISM Code at Branch office in Japan and Overseas                      | 1 July 1997<br>SMD  |
| 2 1 8 | (for Japanese flag vessels, available only in Japanese)                                                                           | ---                 |
| 2 2 0 | Work on Bulk Carrier Safety in IMO and IACS                                                                                       | 30 July 1997<br>BCD |
| 2 2 1 | Alternative survey scheme of propeller shaft based on approval preventive maintenance system                                      | 15 Aug. 1997<br>SVD |
| 2 2 2 | Early application for approval of Cargo Securing Manual                                                                           | 20 Aug. 1997<br>HLD |
| 2 2 3 | Special Requirements Relating to INMARSAT-C Ship Earth Stations of Singapore GMDSS Ships                                          | 10 Sep. 1997<br>EQD |
| 2 2 4 | Authorizations given to NK to approve Cargo Securing Manuals                                                                      | 10 Sep. 1997        |
| 2 2 5 | Statutory surveys for ships changing to Malaysian registry                                                                        | 20 Sep. 1997<br>BCD |
| 2 2 6 | (for Japanese flag vessels, available only in Japanese)                                                                           | ---                 |

| N o . | Subject                                                                                              | Date/<br>Contact        |
|-------|------------------------------------------------------------------------------------------------------|-------------------------|
| 2 2 7 | Guidelines for a Structure of an Integrated System of Contingency Planning for Shipboard Emergencies | 2 Oct. 1997<br><br>SMD  |
| 2 2 8 | IMO Conventions enter into force in 1998                                                             | 13 Oct. 1997<br><br>BCD |
| 2 2 9 | Guidance for IACS Auditors to the ISM Code                                                           | 1 Oct. 1997<br><br>SMD  |
| 2 3 0 | Registration will prioritise ISM Code Certifications                                                 | 13 Oct. 1997<br><br>SMD |
| 2 3 1 | Definition of Bulk Carrier in SOLAS IX for ISM Code Certifications                                   | 15 Oct. 1997<br><br>SMD |
| 2 3 2 | Summary of revised SOLAS Chapter III Entering Into Force on 1 July 1998                              | 28 Oct. 1997<br><br>EQD |

Contents of No. 157/187/190/207 might be amended in near future. Please confirm Equip Department whether there are some amendments when these papers are referred to.