

Subject :

LIST OF CURRENT NK
TECHNICAL INFORMATION

NK TECHNICAL INFORMATION

No. : 344

Date : 1 January 2000

To: Shipowners and Shipbuilders concerned

Enclosed is an updated list of the prevailing back issues of NK TECHNICAL INFORMATION issued by NK as of 1 July 2000.

Although we hope this list be helpful to you, please be aware that NK Technical Information does not always cover all details of the special requirements of each Administration regarding international conventions. Should you have any other questions and need further information, please feel free to contact each department in charge at NK Head Office as given below.

<u>Name of Department</u>	<u>Abb.</u>	<u>Tel. No.</u>	<u>Fax No.</u>
Hull Dept.	HLD	81-3-5226-2017/18	81-3-5226-2019
Material and Equipment Dept.	EQD	81-3-5226-2020	81-3-5226-2019
Machinery Dept.	MCD	81-3-5226-2022/23	81-3-5226-2024
Development Dept.	DVD	81-3-5226-2025	81-3-5226-2024
Survey Dept.	SVD	81-3-5226-2027/28	81-3-5226-2029
Classification Dept.	CLD	81-3-5226-2032/33	81-3-5226-2030
Ship Management Dept.	SMD	81-3-5226-2034	81-3-5226-2030
Business Coordination Dept.	BCD	81-3-5226-2038	81-3-5226-2039
Marine & Industrial Service Dept.	MID	81-3-5226-2041	81-3-5226-2039
Y2K Project Team	—	81-3-5226-2020	81-3-5226-2019

Please contact Business Coordination Department should you need a copy of any back issue of NK Technical Information.

ClassNK

NIPPON KAIJI KYOKAI
4-7, KIOI-CHO, CHIYODA-KU,
TOKYO 102-8567, JAPAN.

TELEX: J22975 CLASSNK
2324280 CLASNKJ
CABLE: CLASSNK TOKYO

LIST OF CURRENT NK TECHNICAL INFORMATION

No .	Subject	Date/ Contact
5 3	Annual Inspections of Crew Lifts fitted on board Greek Flag Ships	5 Nov. 1986 EQD
1 0 9	NK Emergency Technical Assistance Service (ETAS)	10 Dec. 1992 SVD
1 1 1	Survey Request from the Port State under Port State Control	4 Feb. 1993 SVD
1 3 6	Additional Requirements of GMDSS for Greek flag ships	10 May 1994 EQD
1 4 4	Arrangements for Supplying Heading Information to Emergency Steering Positions for Non-Japanese Ships	15 Aug. 1994 EQD
1 4 9	Two-way VHF Radiotelephone Apparatus installed on board in accordance with Requirements of 1988 Amendments to 1974 SOLAS	24 Oct. 1994 EQD
1 5 2	Measures for Providing Heading Information at Emergency Steering Positions	31 Oct. 1994 EQD
1 5 5	Shipboard Oil Pollution Emergency Plan	14 Dec. 1994 SVD
1 5 6	Measures for Providing Heading Information at Emergency Steering Positions	10 Jan. 1995 EQD
1 6 0	Requirements of Maltese Government for Immersion Suits and Thermal Protective Aids	28 Apr. 1995 EQD
1 6 5	Condition Survey for Bulk Carriers over 18 years old of ages entering into Brazilian Ports (No.2)	27 Jul. 1995 MID
1 6 8	Good Preparation For Surveys & Enhanced Maintenance On Board Ships	8 Sep. 1995 SVD
1 6 9	Required Qualifications and Numbers of Radio Personnel on board GMDSS Ships	20 Oct. 1995 EQD
1 7 1	Exemption from Installation of Radio Direction Finder and Radio equipment for Homing on Bahamas Flag Ships	28 Dec. 1995 EQD
1 7 2	A Pump Used Both for an Oily Water Separator and Sludge Transfer	21 Dec. 1995 SVD
1 8 1	Marine Safety Initiatives Implemented by All IACS Member Societies	15 May 1996 BCD

No .	Subject	Date/ Contact
1 8 3	Exemption from Installation of a Radio Direction Finder & Radio Equipment for Homing on Barbados Flag Ships	8 May 1996 EQD
1 8 5	Suspension of Class	1 Jun. 1996 CLD
1 8 6	Revised Qualifications and Number of Radio Personnel Required on Board Vanuatu GMDSS Ships	25 Jun. 1996 EQD
1 9 0	Positioning of Sidelights on Hong Kong Flag Container Ships	25 Jul. 1996 EQD
1 9 1	Requirements of GMDSS for Hong Kong Registered Ships	30 Jul. 1996 EQD
1 9 3	Qualifications and Numbers of Radio Personnel Required on board Malaysian Flag and Myanmar Flag GMDSS Ships	5 Aug. 1996 EQD
1 9 5	Exemption from the Requirements of Radio Direction - Finding Apparatus, Automatic Radar Plotting Aid, Radar, etc. of the Liberian and Marshall Islands Flag Ships	20 Aug. 1996 SVD
1 9 8	Implementation of Maneuvering Performance Capability Tests for Tank Vessels without Double Hulls Carrying Oils of 5,000 Gross Tonnage And More Which Enter into U.S. Waters	15 Oct. 1996 MID
1 9 9	Maintenance for Electro-Hydraulic Cranes	11 Nov. 1996 EQD
2 0 3	New Requirements for Bulk Carrier	25 Dec. 1996 SVD
2 0 5	Qualifications and Number of Radio Personnel Required on board Libyan Flag GMDSS Ships	6 Feb. 1997 EQD
2 0 8	Reserve Sources of Energy for GMDSS Radio Equipment on Board Greek Flag Ships	25 Feb. 1997 EQD
2 0 9	Exemption from Installation of a Radio Direction Finder on Singapore Flag Ships	28 Feb. 1997 EQD
2 1 2	Languages To Be Used On Safety Plans On Board Malaysian Flag Vessels	10 Apr. 1997 BCD
2 1 6	Exemption from Requirements of Chapter IV and V of SOLAS Convention for Panamanian Flag Ships	30 June 1997 EQD
2 2 3	Special Requirements Relating to INMARSAT-C Ship Earth Stations of Singapore GMDSS Ships	10 Sep. 1997 EQD
2 2 6	Guidelines for Port State Control Inspection on ISM Code	1 Oct. 1997 SMD

No.	Subject	Date/ Contact
2 2 7	Guidelines for a Structure of an Integrated System of Contingency Planning for Shipboard Emergencies	2 Oct. 1997 SMD
2 2 9	Guidance for IACS Auditors to the ISM Code	1 Oct. 1997 SMD
2 3 4	Implementation Scheme of Upgraded Requirements for Existing Bulk Carriers	11 Nov. 1997 SVD
2 3 5	Crew Accommodations of Singapore Ships	30 Nov. 1997 EQD
2 3 8	Application of ILO Conventions and to Crew Accommodations of Liberian Ships and Marshall Islands Ships	18 Dec. 1997 EQD
2 3 9	Implementation and Enforcement of ISM Code by US Coast Guard	19 Dec. 1997 SMD
2 4 0	Handling of Ship Type for Multi-purpose Ships Regarding ISM Code Certification	20 Jan. 1998 SMD
2 4 2	Implementation and Enforcement of ISM Code by US Coast Guard (Part 2)	21 Jan. 1998 SMD
2 4 5	IMO Conventions Enter into Force in 1999	5 Feb. 1998 BCD
2 4 6	Implementation Scheme of Upgraded Requirements for Existing Bulk Carriers (Review of Implementation Timetable and Clarification of Application of Loading Computer)	2 Apr. 1998 SVD
2 5 0	Provision with Loading/Unloading Sequence for Existing Bulk Carrier	15 Apr. 1998 HLD
2 5 1	Safe Access to Tanker Bow and Tank Venting System Required for Existing Tankers under Amendment to SOLAS 74	6 Apr. 1998 HLD
2 5 2	The Colour of Coating Applied to Seawater Ballast Tanks of Oil Tankers and Bulk Carriers	17 Apr. 1998 HLD
2 5 3	Sea Areas A1 and A2 and Required Radio Personnel on board Singapore Flag GMDSS Ships Specified by Singapore Government	23 Apr. 1998 EQD
2 5 5	MARPOL 73/78 New Annex VI "Regulations for the Prevention of Air Pollution from Ships"	1 May 1998 DVD
2 5 7	Amendments to IBC/BCH Codes for Existing Chemical Tankers with Non-Japanese Flag	22 May 1998 HLD
2 5 8	Amendments to IGC/GC Codes for Existing Gas Carriers with Non-Japanese Flag	22 May 1998 HLD

No.	Subject	Date/ Contact
2 6 0	Definition of Bulk Carrier in SOLAS for ISM Code Certifications (Part 3)	1 June 1998 SMD
2 6 1	Amendments to IBC/BCH Codes for Existing Chemical Tankers with Non-Japanese Flag – Correction	1 June 1998 HLD
2 6 5	(for Japanese flag vessels, available only in Japanese)	---
2 6 6	Required Radio Personnel on Board Belizean, Qatari & Sri Lankan Flag GMDSS Ships	30 Jun. 1998 EQD
2 6 7	Close-up Survey for Longitudinal in Double Bottom and Bilge Hopper-Tanks of Large Bulk Carriers	18 Jun. 1998 SVD
2 7 1	Guidelines on Tokyo MOU Port State Control Inspection on the ISM Code	21 Jul. 1998 SMD
2 7 4	IMO Resolutions on the 20th Session of the Assembly Related to the ISM Code	27 Jul. 1998 SMD
2 7 5	Radio Logbooks Required on Board Liberian and Greek Flag GMDSS Ships	12 Aug. 1998 EQD
2 7 7	The Year 2000 Problem and GPS Rollover Problems	11 Aug. 1998 Y2K Project Team
2 7 8	The Year 2000 Problem and GPS Rollover Problems 2	31 Aug. 1998 Y2K Project Team
2 7 9	The Year 2000 Problem and GPS Rollover Problems 3	10 Sep. 1998 Y2K Project Team
2 8 0	Fire Extinguishing Arrangement for Paint Lockers and Flammable Liquid Lockers of Liberian Flag Ships	26 Aug. 1998 EQD
2 8 3	IMO conventions enter into force in 2002 (Part 1)	16 Sep. 1999 BCD
2 8 5	(for Japanese flag vessels, available only in Japanese)	---
2 8 7	Radar & Echo – Sounding Equipment to Be Installed on Board Hong Kong Registered Ships	30 Nov. 1998 EQD
2 8 9	Abstract of 96 SOLAS and LSA Code	16 Dec. 1998 EQD
2 9 0	Examinations, Testing and Certification Requirements of USA OSHA for Cargo Gears of Ships Loading/Unloading at USA Ports	15 Dec. 1998 EQD

No .	Subject	Date/ Contact
2 9 2	Condition for Exemption from Application of GMDSS Requirements in Chapter IV of SOLAS Convention	18 Dec. 1998 EQD
2 9 3	Required Radio Personnel on Board Maltese Flag GMDSS Ships	16 Dec. 1998 EQD
2 9 4	Requirements for the Prevention of Pollution by Sewage from Ships for Marshall Islands Flag Vessels ANNEX IV to MARPOL 73/78	22 Dec. 1998 MID
2 9 8	Radio Personnel Required for Panamanian Flag GMDSS Ships	1 Feb. 1999 EQD
2 9 9	A Representative of the Company for the ISM Code Shipboard Audit	10 Feb. 1999 SMD
3 0 0	Port State Control in China	8 Mar. 1999 SVD
3 0 2	Guidance for IACS Auditors to the ISM Code (Revision) (Year 2000 Problems)	10 Mar. 1999 SMD
3 0 3	Certificate Required for Registration of Panamanian Flag Vessel (in relation to application of ISM Code)	15 Mar. 1999 SMD
3 0 4	Required Radio Personnel on Board Bolivian, UAE and Bahamian Flag GMDSS Ships	25 Mar. 1999 EQD
3 0 6	Requirements for Gas Carriers Which Will Enter Indian Ports	7 Apr. 1999 SVD
3 0 7	MARPOL 73/78 Annex V "Regulations for the Prevention of Pollution by Garbage from Ships"	19 Apr. 1999 MID
3 0 8	How TO Use EPIRB at A Ship In Distress	26 April 1999 SVD
3 0 9	The Year 2000 and GPS Rollover Problem (Part 4)	15 Apr. 1999 Y2K Project Team
3 1 0	Revised Cargo Gear Regulations of Australia	10 May 1999 EQD
3 1 1	MARPOL 73/78 Annex VI Reg.16 Shipboard Incineration Confirmation of Installed Date of Incinerator	17 May 1999 MCD
3 1 2	Remedy of Mechanical and Electrical Damages Occurred in Greece	21 May 1999 SVD
3 1 3	Canadian Code to be Applied to Ships That Carry a Timber Deck Cargo Into or Out of Canada	1 June 1999 EQD

N o .	Subject	Date/ Contact
3 1 4	Training and Drills of Lifesaving on Board Netherlands Flag Ships	28 May 1999 EQD
3 1 5	Means for Rapid Safe Recovery of Rescue Boats of Hong Kong Registered Ships	28 May 1999 EQD
3 1 6	The colour of protective coating applied to seawater ballast tanks of oil tankers And bulk carriers	15 June 1999 BCD
3 1 7	List of Current NK Technical Information	1 July 1999 BCD
3 1 8	Corrective action required by PSC with regard to ISM-related non-conformity caused by poor maintenance of ship and its equipment	1 July 1999 SMD
3 2 0	The year 2000 and GPS Rollover Problem (Part 5)	1 July 1999 EQD
3 2 1	Entry into force of the Harmonized System of Survey and Certificate (HSSC)	28 July 1999 BCD
3 2 2	Maintenance of Sea Water/Sanitary Piping in Engine Room and Sea Water Piping on Weather Deck	4 Aug 1999 BCD
3 2 3	Conformity Assessment/Certificate under Marine Equipment Directive	30 July 1999 EQD
3 2 4	Venting System of Combined Oil/Chemical Tankers Required under SOLAS 74 (Ref: NK Technical Information No.305)	9 Aug. 1999 HLD
3 2 5	Rescue boat launching appliances on board Netherlands Flag Ships	24 Aug. 1999 EQD
3 2 6	Methods of measurement of the density of bulk cargoes with respect to Application of SOLAS chapter VII	1 Sep. 1999 BCD
3 2 7	Entry into force of the Harmonized System of Survey and Certification (HSSC)- Correction	6 Sep. 1999 BCD
3 2 8	Implementation recently adopted convention by IMO	13 Sep. 1999 BCD
3 2 9	Introduction of SI units	20 Sep. 1999 CLD
3 3 0	Assessment of Year 2000 Compliance Programs	17 Sep. 1999 SMD
3 3 1	Surveys of the launching appliance and on-load release gear for lifeboat and Rescue boat on board Malta flag vessels	30 Sep. 1999 EQD

N o .	Subject	Date/ Contact
3 3 2	Cyprus Requirement with regard to Five Control Life Saving Appliances Plans	1 Oct. 1999 BCD
3 3 3	Requirements to be met by vessels entering into Greek Ports carrying sold Cargo in bulk	11 Oct. 1999 BCD
3 3 4	(for Japanese flag vessels, available only in Japanese)	---
3 3 5	Rescue boat launching appliances on board Netherlands Flag Ships	12 Oct. 1999 EQD
3 3 6	Required Radio Personnel on Board Bahrain Flag GMDSS Ships	1 Nov. 1999 EQD
3 3 7	Correction of Technical Information No.328	22 Oct. 1999 BCD
3 3 8	Safe Working Load of the cargo handling appliances under SI units	15 Nov. 1999 EQD
3 3 9	Amendment of Rules "Condition of Service for Classification of Ships and Registration of Installation"	25 Nov. 1999 DVD
3 4 0	"Launching at 5 knots" test for lifeboat and rescue boat at sea trial	30 Nov. 1999 SVD
3 4 1	Exemption from Installation of a Radio Direction Finder	20 Dec. 1999 EQD
3 4 2	(for Japanese flag vessels, available only in Japanese)	---
3 4 3	MARPOL 73/78 Annex VI Reg.16 Shipboard Incineration Interpretation of "installed on board"	7 Dec. 1999 MCD
3 4 4	List of Current NK Technical Information	1 Jan. 1999 BCD
