

Subject :

LIST OF CURRENT NK
TECHNICAL INFORMATION

NK TECHNICAL INFORMATION

No. : 391

Date : 1 January, 2001

To: Shipowners and Shipbuilders concerned

Please find enclosed an updated list of the prevailing back issues of NK TECHNICAL INFORMATION issued by NK as of 1 January 2001, together with a list of all invalid NK TECHNICAL INFORMATION that have deleted from the previous list for your reference.

Although we hope the lists be helpful to you, please be aware that NK Technical Information does not always cover all details of the special requirements of each Administration regarding international conventions. Should you have any other questions and need further information, please feel free to contact each department in charge at NK Head Office as given below.

<u>Name of Department</u>	<u>Abb.</u>	<u>Tel. No.</u>	<u>Fax No.</u>
Hull Dept.	HLD	81-3-5226-2017/18	81-3-5226-2019
Material and Equipment Dept.	EQD	81-3-5226-2020	81-3-5226-2019
Machinery Dept.	MCD	81-3-5226-2022/23	81-3-5226-2024
Survey Dept.	SVD	81-3-5226-2027/28	81-3-5226-2029
Classification Dept.	CLD	81-3-5226-2032/33	81-3-5226-2030
Ship Management Dept.	SMD	81-3-5226-2034	81-3-5226-2030
Business Coordination Dept.	BCD	81-3-5226-2038	81-3-5226-2039
Marine & Industrial Service Dept.	MID	81-3-5226-2041	81-3-5226-2039
Testing Machine Division	TMD	81-43-294-6753	81-43-294-5706

Please contact Business Coordination Department should you need a copy of any back issue of NK Technical Information.

ClassNK NIPPON KAIJI KYOKAI
4-7, KIOI-CHO, CHIYODA-KU,
TOKYO 102-8567, JAPAN.

LIST OF CURRENT NK TECHNICAL INFORMATION

No.	Subject	Date/ Contact
5 3	Annual Inspections of Crew Lifts fitted on board Greek Flag Ships	5 Nov. 1986 EQD
1 0 9	NK Emergency Technical Assistance Service (ETAS)	10 Dec. 1992 SVD
1 3 6	Additional Requirements of GMDSS for Greek flag ships	10 May 1994 EQD
1 4 4	Arrangements for Supplying Heading Information to Emergency Steering Positions for Non-Japanese Ships	15 Aug. 1994 EQD
1 4 9	Two-way VHF Radiotelephone Apparatus installed on board in accordance with Requirements of 1988 Amendments to 1974 SOLAS	24 Oct. 1994 EQD
1 5 2	Measures for Providing Heading Information at Emergency Steering Positions	31 Oct. 1994 EQD
1 5 6	Measures for Providing Heading Information at Emergency Steering Positions	10 Jan. 1995 EQD
1 6 0	Requirements of Maltese Government for Immersion Suits and Thermal Protective Aids	28 Apr. 1995 EQD
1 6 5	Condition Survey for Bulk Carriers over 18 years old of ages entering into Brazilian Ports (No.2)	27 Jul. 1995 MID
1 6 8	Good Preparation For Surveys & Enhanced Maintenance On Board Ships	8 Sep. 1995 SVD
1 6 9	Required Qualifications and Numbers of Radio Personnel on board GMDSS Ships	20 Oct. 1995 EQD
1 7 1	Exemption from Installation of Radio Direction Finder and Radio equipment for Homing on Bahamas Flag Ships	28 Dec. 1995 EQD
1 7 2	A Pump Used Both for an Oily Water Separator and Sludge Transfer	21 Dec. 1995 SVD
1 8 3	Exemption from Installation of a Radio Direction Finder & Radio Equipment for Homing on Barbados Flag Ships	8 May 1996 EQD
1 8 5	Suspension of Class	1 Jun. 1996 CLD
1 8 6	Revised Qualifications and Number of Radio Personnel Required on Board Vanuatu GMDSS Ships	25 Jun. 1996 EQD
1 9 0	Positioning of Sidelights on Hong Kong Flag Container Ships	25 Jul. 1996 EQD

No.	Subject	Date/ Contact
1 9 1	Requirements of GMDSS for Hong Kong Registered Ships	30 Jul. 1996 EQD
1 9 3	Qualifications and Numbers of Radio Personnel Required on board Malaysian Flag and Myanmar Flag GMDSS Ships	5 Aug. 1996 EQD
1 9 8	Implementation of Maneuvering Performance Capability Tests for Tank Vessels without Double Hulls Carrying Oils of 5,000 Gross Tonnage And More Which Enter into U.S. Waters	15 Oct. 1996 MID
1 9 9	Maintenance for Electro-Hydraulic Cranes	11 Nov. 1996 EQD
2 0 5	Qualifications and Number of Radio Personnel Required on board Libyan Flag GMDSS Ships	6 Feb. 1997 EQD
2 0 8	Reserve Sources of Energy for GMDSS Radio Equipment on Board Greek Flag Ships	25 Feb. 1997 EQD
2 2 3	Special Requirements Relating to INMARSAT-C Ship Earth Stations of Singapore GMDSS Ships	10 Sep. 1997 EQD
2 2 7	Guidelines for a Structure of an Integrated System of Contingency Planning for Shipboard Emergencies	2 Oct. 1997 SMD
2 2 9	Guidance for IACS Auditors to the ISM Code	1 Oct. 1997 SMD
2 3 5	Crew Accommodations of Singapore Ships	30 Nov. 1997 EQD
2 3 8	Application of HLO Conventions and to Crew Accommodations of Liberian Ships and Marshall Islands Ships	18 Dec. 1997 EQD
2 5 1	Safe Access to Tanker Bow and Tank Venting System Required for Existing Tankers under Amendment to SOLAS 74	6 Apr. 1998 HLD
2 5 3	Sea Areas A1 and A2 and Required Radio Personnel on board Singapore Flag GMDSS Ships Specified by Singapore Government	23 Apr. 1998 EQD
2 6 0	Definition of Bulk Carrier in SOLAS for ISM Code Certifications (Part 3)	1 June 1998 SMD
2 6 6	Required Radio Personnel on Board Belizean, Qatari & Sri Lankan Flag GMDSS Ships	30 Jun. 1998 EQD
2 6 7	Close-up Survey for Longitudinal in Double Bottom and Bilge Hopper-Tanks of Large Bulk Carriers	18 Jun. 1998 SVD
2 7 1	Guidelines on Tokyo MOU Port State Control Inspection on the ISM Code	21 Jul. 1998 SMD
2 7 4	IMO Resolutions on the 20th Session of the Assembly Related to the ISM Code	27 Jul. 1998 SMD

No.	Subject	Date/ Contact
2 7 5	Radio Logbooks Required on Board Liberian and Greek Flag GMDSS Ships	12 Aug. 1998 EQD
2 8 0	Fire Extinguishing Arrangement for Paint Lockers and Flammable Liquid Lockers of Liberian Flag Ships	26 Aug. 1998 EQD
2 8 5	(for Japanese flag vessels, available only in Japanese)	---
2 8 7	Radar & Echo – Sounding Equipment to Be Installed on Board Hong Kong Registered Ships	30 Nov. 1998 EQD
2 8 9	Abstract of 96 SOLAS and LSA Code	16 Dec. 1998 EQD
2 9 0	Examinations, Testing and Certification Requirements of USA OSHA for Cargo Gears of Ships Loading/Unloading at USA Ports	15 Dec. 1998 EQD
2 9 2	Condition for Exemption from Application of GMDSS Requirements in Chapter IV of SOLAS Convention	18 Dec. 1998 EQD
2 9 4	Requirements for the Prevention of Pollution by Sewage from Ships for Marshall Islands Flag Vessels ANNEX IV to MARPOL 73/78	22 Dec. 1998 MID
2 9 8	Radio Personnel Required for Panamanian Flag GMDSS Ships	1 Feb. 1999 EQD
2 9 9	A Representative of the Company for the ISM Code Shipboard Audit	10 Feb. 1999 SMD
3 0 3	Certificate Required for Registration of Panamanian Flag Vessel (in relation to application of ISM Code)	15 Mar. 1999 SMD
3 0 4	Required Radio Personnel on Board Bolivian, UAE and Bahamian Flag GMDSS Ships	25 Mar. 1999 EQD
3 0 6	Requirements for Gas Carriers Which Will Enter Indian Ports	7 Apr. 1999 SVD
3 0 7	MARPOL 73/78 Annex V “Regulations for the Prevention of Pollution by Garbage from Ships”	19 Apr. 1999 MID
3 1 0	Revised Cargo Gear Regulations of Australia	10 May 1999 EQD
3 1 1	MARPOL 73/78 Annex VI Reg.16 Shipboard Incineration Confirmation of Installed Date of Incinerator	17 May 1999 MCD
3 1 2	Remedy of Mechanical and Electrical Damages Occurred in Greece	21 May 1999 SVD
3 1 3	Canadian Code to be Applied to Ships That Carry a Timber Deck Cargo Into or Out of Canada	1 June 1999 MID

No.	Subject	Date/ Contact
3 1 4	Training and Drills of Lifesaving on Board Netherlands Flag Ships	28 May 1999 EQD
3 1 5	Means for Rapid Safe Recovery of Rescue Boats of Hong Kong Registered Ships	28 May 1999 EQD
3 1 8	Corrective action required by PSC with regard to ISM-related non-conformity caused by poor maintenance of ship and its equipment	1 July 1999 SMD
3 2 2	Maintenance of Sea Water/Sanitary Piping in Engine Room and Sea Water Piping on Weather Deck	4 Aug 1999 SVD
3 2 4	Venting System of Combined Oil / Chemical Tankers Required under SOLAS 74 (Ref: NK Technical Information No.305)	9 Aug. 1999 HLD
3 2 5	Rescue boat launching appliances on board Netherlands Flag Ships	24 Aug. 1999 EQD
3 3 2	Cyprus Requirement with regard to Five Control Life Saving Appliances Plans	1 Oct. 1999 BCD
3 3 3	Requirements to be met by vessels entering into Greek Ports carrying sold Cargo in bulk	11 Oct. 1999 BCD
3 3 4	(for Japanese flag vessels, available only in Japanese)	---
3 3 5	Rescue boat launching appliances on board Netherlands Flag Ships	12 Oct. 1999 EQD
3 3 6	Required Radio Personnel on Board Bahrain Flag GMDSS Ships	1 Nov. 1999 EQD
3 3 8	Safe Working Load of the cargo handling appliances under SI units	15 Nov. 1999 EQD
3 4 0	"Launching at 5 knots" test for lifeboat and rescue boat at sea trial	30 Nov. 1999 SVD
3 4 1	Exemption from Installation of a Radio Direction Finder	20 Dec. 1999 EQD
3 4 2	(for Japanese flag vessels, available only in Japanese)	---
3 4 3	MARPOL 73/78 Annex VI Reg.16 Shipboard Incineration Interpretation of "installed on board"	7 Dec. 1999 MCD
3 4 5	Treatment of indent on deck crane or derrick boom	24 Dec. 1999 SVD
3 4 6	Conformity Assessment / Certification under EC Marine Equipment Directive	17 Jan. 2000 EQD

No.	Subject	Date/ Contact
3 4 7	Guideline for issuance of the Statutory Certificates under the Harmonized System of Survey and Certification (HSSC)	20 Jan.2000 SVD
3 4 8	Revised Requirements for Radio Personnel for Philippines and Saudi Arabian Flag GMDSS Ships	18 Jan.2000 EQD
3 4 9	Interpretations of Chapter III of 1996 Amendments to 1974 SOLAS and LSA Code, and Survey / Testing Procedures	21 Jan.2000 EQD
3 5 0	Examination and certification of shipboard incinerators	21 Jan.2000 EQD
3 5 1	BC Code Fitness Certification	1 Feb.2000 EQD
3 5 2	Radar to be installed on board Panamanian Ships	17 Mar.2000 EQD
3 5 3	Regulations for the Prevention of Pollution by Sewage from ships for Greek flag Vessels (ANNEX IV to MARPOL 73/78)	31 Mar.2000 MID
3 5 4	An amendment to the Regulations of California for Oil Spill Prevention and Response	7 Apr.2000 BCD
3 5 5	(for Japanese flag vessels, available only in Japanese)	---
3 5 7	Overhauling and operational test of lifeboat on-load release gear for Bahamas flag ships	25 Apr.2000 EQD
3 5 8	Gross Tonnage for Determination of Application of GMDSS Requirements to Panamanian Ships	28 Apr.2000 EQD
3 5 9	Procedure for Responding to Digital Selective Calling(DSC) Distress Alerts by Hong Kong Registered Ships	16 May 2000 EQD
3 6 0	Revised Requirements for Radio Personnel for Maltese Flag GMDSS Ships	16 May 2000 EQD
3 6 1	Surveys of Life-Saving Appliances for the Netherlands Flag Ships	15 May 2000 EQD
3 6 2	Radio Inspectors arranged at Safety Radio Surveys of Non-Japanese Flag Ships	1 Apr. 2000 EQD
3 6 3	Introduction of HSSC to the Maltese vessels	2 Jun. 2000 BCD
3 6 4	The exemption from damage Stability requirements for the existing bulk carriers	15 Jun. 2000 SVD
3 6 5	Introduction of HSSC to the Maltese vessels	19 Jun. 2000 BCD

No.	Subject	Date/ Contact
3 6 6	Revised Requirements for Radio Personnel for Greek Flag GMDSS ships	20 Jun. 2000 EQD
3 6 7	Timber deck cargo in the context of damage stability requirements, Interpretation on Paragraph 1 of Regulation 25-8, Chapter II -1, SOLAS	30 Jun. 2000 HLD
3 6 8	Revised Requirements for Radio Personnel for Kuwait Flag GMDSS ships	10 Jul. 2000 EQD
3 7 1	(for Japanese flag vessels, available only in Japanese)	---
3 7 2	Launching appliance and lifeboat on-load release gear on board Malta flag ships	25 Aug. 2000 EQD
3 7 3	Inflatable liferafts, marine evacuation systems and hydrostatic release units on board Greek flag ships	25 Aug. 2000 EQD
3 7 4	Partial Exemption from the Requirements for GMDSS for Greek Flag GMDSS Ships Engaging on Voyages in the Mediterranean and Black Sea	1 Sep. 2000 EQD
3 7 5	Method for calculation capacity of accumulating batteries used for a reserve source or sources of energy of radio installation on board the Philippines flag GMDSS ships	1 Sep. 2000 EQD
3 7 6	Implementation of recently adopted conventions by IMO	18 Sep. 2000 BCD
3 7 7	Oil Analysis as Part of the Preventive Maintenance System for Oil Lubricated Propeller Shafts	21 Sep. 2000 MID
3 7 8	Exemption for Installation of a Radio Direction Finder on Libyan Ships	28 Sep. 2000 EQD
3 7 9	Voyage Repairs and Maintenance	17 Oct. 2000 SVD
3 8 0	Books and Documents Required on Board the Greek Ships Sailing within the Limits of Sea Area A1	10 Nov. 2000 EQD
3 8 1	Equivalent Arrangement to Installation of a Radio Direction Finder on Barbadian Ships	10 Nov. 2000 EQD
3 8 2	List of Radio Firms and Radio Installation Inspection Service Companies	15 Nov. 2000 EQD
3 8 3	Requirements adopted by IMO at MEPC 45	16 Nov. 2000 BCD
3 8 4	Equivalent Arrangement to Installation of a Radio Direction Finder on Danish Ships	27 Nov. 2000 EQD
3 8 5	Maximum shock-cooled flue gas temperature of shipboard incinerators	1 Dec. 200 EQD

No.	Subject	Date/ Contact
3 8 6	Amendments of Supplement to IOPP Certificate (Form A and B)	14 Dec. 2000 SVD
3 8 7	Machinery Verification Runs at the time of drydocking and at the completion of significant repairing	15 Dec. 2000 SVD
3 8 8	PSC Focused Inspection Program to be conducted by AMSA	25 Dec. 2000 SVD
3 8 9	(for Japanese flag vessels, available only in Japanese)	---
3 9 0	Shipboard Marine Pollution Emergency Plan for noxious liquid substance (SMPEP)	28 Dec. 2000 SVD

VOID

LIST OF INVALID NK TECHNICAL INFORMATION

No.	Subject	Date/ Contact
1 5 5	Shipboard Oil Pollution Emergency Plan	14 Dec. 1994 B SVD
2 5 0	Provision with Loading/Unloading Sequence for Existing Bulk Carrier	15 Apr. 1998 B HLD
2 5 7	Amendments to IBC/BCH Codes for Existing Chemical Tankers with Non-Japanese Flag	22 May 1998 A HLD
2 5 8	Amendments to IGC/GC Codes for Existing Gas Carriers with Non-Japanese Flag	22 May 1998 A HLD
3 0 0	Port State Control in China	8 Mar. 1999 B SVD
3 0 8	How TO Use EPIRB at A Ship In Distress	26 April 1999 B SVD
3 3 1	Surveys of the launching appliance and on-load release gear for lifeboat and Rescue boat on board Malta flag vessels	30 Sep. 1999 B EQD
3 5 6	Resolutions adopted by IMO Assembly at its 21 st session	5 Apr. 2000 B BCD
3 6 9	List of Current NK Technical Information	1 Jul. 2000 B BCD
3 7 0	Paris MOU PSC Concentrated Inspection Campaign on Oil Tankers over 15 years old	31 Jul. 2000 B SVD

< JUDGEMENT >

- A) Information which has been incorporated into our rules and other publicised regulations, therefore, it is not necessary to maintain its validity.
- B) Information which has not been incorporated into our rules, etc. and is no longer considered necessary.

※※※